

Date: 4 October 2021

Dear Sir or Madam

Reference: 607222

**A12 JUNCTIONS 15 to 19 (Webb Farm Interchange to Boreham Interchange)
NOTIFICATION OF START OF WORK - NORTHBOUND**

As our concrete road surface repairs to the A12 southbound carriageway are progressing well, we will now be moving to the northbound carriageway ahead of schedule, with work starting there in October 2021 instead of November 2021.

Work will start on Monday 18 October 2021 and is expected to be complete during December 2021, subject to weather conditions. To do the repairs safely we will need to have overnight road closures on week nights, with a signed diversion route in place.

Road closures

Northbound from Monday 18 October 2021 until December 2021:

- 9pm until 5am on Mondays to Thursdays
- 9.30pm on Fridays until 6am on Saturdays.

Note: We monitor the traffic flow and may close the A12 from 8pm to start our work earlier if there are low levels of traffic using the road. This will help complete our repairs quicker.

Please find a map showing the diversion route on the next page.

Once our repairs are completed, it will extend the road surface life by up to 10 years. They will provide a safer, smooth road surface and we expect the noise level from the surfacing will be improved.


I will advise you of any changes to our work programme. Alternatively, for more information, please call the Highways England Customer Contact Centre on 0300 123 5000, or email info@highwaysengland.co.uk. Regular updates will be made on the A12 project webpage at www.highwaysengland.co.uk/A12concrete. Or follow us on Twitter @HighwaysEAST.

Yours sincerely

JEriksen

John Eriksen on behalf of National Highways
Community and Communication Manager at VolkerFitzpatrick

Diversion Route Map



We expect the diversion to add approximately 25 minutes to the usual journey time.

Northbound Diversion Route

Monday 18 October 2021 until December 2021

Monday to Thursday from 9pm until 5am. Friday to Saturday from 9pm until 6am.

Drivers heading north should leave the A12 at junction 15 and join the A414. Follow the A414 and then join the A1016 (Westway). Follow the A1016 and then join the A130 to re-join the A12 at J19 Boreham Interchange. A signed diversion route will be in place.

Please follow the signed diversion route.